

附件 1:

历史遗留矿山核查认定明细表

序号	图斑编号	图斑大类	矿山位置	修复主体	图斑面积 (平方米)	主要拐点坐标	备注
1	3201160730107001	历史遗留矿山	江苏省南京市六合区葛塘街道前程社区	政府	50387.28	118.701349,32.261653 118.702481,32.261589 118.703108,32.261653 118.703216,32.261771 118.703339,32.262292 118.703548,32.263595 118.703672,32.264234 118.703672,32.264486 118.702728,32.264577 118.702186,32.264673 118.701885,32.264502 118.701842,32.264073 118.702373,32.263751 118.702003,32.263322 118.701134,32.263069 118.701129,32.262774 118.702331,32.262858 118.701378,32.262619 118.701279,32.261777 118.701349,32.261653	该图斑由自然资源部下发至南京市六合区,实际位于江北新区境内,后期修复方式为:自然恢复。

2	3201160730107002	历史遗留矿山	江苏省南京市六合区葛塘街道前程社区	政府	26597.85	118. 701901, 32. 267409 118. 702207, 32. 267425 118. 702717, 32. 267227 118. 702829, 32. 266267 118. 703232, 32. 265854 118. 703269, 32. 265741 118. 703108, 32. 265419 118. 703452, 32. 265441 118. 703693, 32. 265298 118. 703747, 32. 265129 118. 703656, 32. 265061 118. 702964, 32. 265049 118. 702627, 32. 265548 118. 702084, 32. 265274 118. 701665, 32. 265532 118. 701665, 32. 266192 118. 701732, 32. 266953 118. 701901, 32. 267409	该图斑由自然资源部下发至南京市六合区,实际位于江北新区境内,后期修复方式为: 自然恢复。
---	------------------	--------	-------------------	----	----------	--	--